

SURE KLEEN

**HOT VAT
and
Jet Spray
for
FERROUS AND CUPREOUS
ALLOYED SURFACES**

EXTRA HEAVY DUTY

CAUTION:

Irritant. Harmful if swallowed. Carefully read all cautions.

77D52 NET CONTENTS POUND(S)

**TO REORDER
PIC**

4408 Glenview Dr
Haltom City, TX 76117
817-281-1474 1-800-359-8031

Sure Kleen is a highly alkaline low foaming product which strips paint, dirt, grease, oil and carbon deposits from ferrous and cupreous alloyed surfaces. It contains detergents to give maximum solution life, penetration and risibility. Sure Kleen has special additives to prevent rust and corrosion after cleaning.

DIRECTIONS:

Hot Vat: General Cleaners $\frac{1}{4}$ to $\frac{1}{2}$ to 1 gallon of water.

Rust or Scale Remover $\frac{1}{2}$ to 1lb to 1 gallon of water.

Maintain temperature at 180 to 200 degrees F. Immersion time will vary depending on severity of contamination, usually $\frac{1}{2}$ to 4 hours.

Jet Spray: $\frac{1}{4}$ to 1lb to 1 gallon of water.

Follow equipment manufacturers operating instructions.

NOTE: Do not use on aluminum, tin, zinc or other non-ferrous metals.

CAUTION:

Keep out of reach of children. Do not take internally. Sure Kleen contains Sodium Hydroxide and can cause severe burns to skin and eyes. So when handling, wear goggles, rubber gloves and apron. In case of skin contact, flush with water for 15 minutes. For eyes, flush with large amounts of water for 15 minutes and get medical attention.