

PEARL BURLY

INDUSTRIAL HAND & SKIN CLEANSER

With Lanolin

SAFELY REMOVES

*Graphite, Carbon

*Paint, Tar

*Grease, Oil

CAUTION: Keep out of reach of children. Rinse empty container before discarding.

10B15 NET CONTENTS GALLON(S)

A pearlescent, biodegradable, industrial hand and skin cleaner and conditioner which safely removes heavy industrial soils with complete gentleness to skin. This product contains lanolin, moisturizers, and emollients that leave the skin soft and moist. Heavy soils such as grease, oil, carbon, fresh inks, paints, and dirt are removed without the harsh solvents which defat the skin, or rough abrasives to scratch and irritate. Authorized by USDA for use in Federally inspected meat and poultry plants.

FOR REMOVAL OF:

Graphite, Carbon, Paint, Tar & Heavy Soils:	Use Undiluted
Light Grease & Oils:	Dilute: 1:1 with water
Soap Dispenser Use:	Dilute: 1:3 with water
Shower Soap:	Dilute: 1:4 with water

Thoroughly rub cleaner into soiled hands, add small amounts of water to work up a lather. Rub skin until thoroughly cleaned, then rinse with clean water.

TO REORDER:

PIC

4408 Glenview Dr, Haltom City, TX 76117
817-281-1474 * 800-359-8031